



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D2690-6
Job Sheet 183908



Part No: D2690-6

Job Qty: 10 ea

Part Name: Lanyard



Part Weight: 0 lbs

Status: Scheduled

Priority: Medium

Job Created: 9/28/18

Job Tracking No:

Due Date: 10/5/18

Created By: Marie Lajeunesse

Type: SOLD

Description:

Note: DWG REV B2 IPP: C C 03.04.04 Reformat; Incorporated D2690-X KJ/RF

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	10 Ea		10/5/18	0.00	0.00	Start Up Small Fab-1		
100	Small Fab	10 pcs		10/5/18	0.00	0.80	Small Fab-2		
110	QC	10 pcs		10/5/18	0.00	0.00	QC5		
120	Packaging	10 pcs		10/5/18	0.00	0.00	Packaging3-1		
130	QC21-SA	10 Ea		10/5/18	0.00	0.00	QC21		

Part Op
Descriptions: 100 - Manufacture as per Dwg D2690

OCT 04 2018
OCT 05 2018

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
CBL-1240	Cable	10 ft (1 ea)	90-Start up Operation	
CBL-460	Loop Sleeve	20 Ea (2 ea)	90-Start up Operation	

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
90-Start up Operation	CBL-1240	10	387	0
	CBL-460	20	379	0

Part Specifications



Container No: S114879



Part: D2690-6

Job No: 183908

Serial No/Batch: S114879

Revision:

Inspector:

Exp Date:

Instructions: Various STC's

1270 Aberdeen St
Hawkesbury, ON K6A 1K7
CANADA
TEL: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

be found.

Plex 9/28/18 11:34 AM Dart.lajeunesse.marie

Date: 10/01/18

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					